




|   |        |
|---|--------|
| <b>SLOT COUNT:</b>                                  | ±1,700 |
| <b>PARKING COUNT:</b>                               |        |
| <b>SURFACE PARKING (73%):</b>                       |        |
| SELF-PARK LOT 1:                                    | ±220   |
| SELF-PARK LOT 2:                                    | ±215   |
| EMPLOYEE LOT 3:                                     | ±295   |
| SELF PARK LOT 4:                                    | ±360   |
| <b>VALET PARKING (27%):</b>                         |        |
| BOGATIN PARCEL:                                     | ±375   |
| <b>TOTAL PARKING:</b>                               | ±1,465 |
| <b>REQUIRED PARKING @ <math>\frac{4}{3}</math>:</b> | ±1,360 |

**Interim Casino**



06 April 2009

© 2009 Cope Linder Architects